

# **Exhibit B**

**Work Order Details**

Work Order Number	469115
Work Order Type	Sewer Backup Investigation
Location	3395 LAKEMEADOW CT, COLETP
Requested by:	LINDA LEIST
Telephone - Home	[REDACTED]
Telephone - Work	.
Customer e-mail	
Comments	<p>Comments #1:  (Copied from Service Request 61321): "Caller: LEIST, LINDA:  Q: Where is the Sewer Backup Occuring?  A: Inside Building  Q: What is the lowest floor of the building that has a Sewer Backup?  A: Basement / Lower Level  Q: Are you experiencing a backup now?  A: YES  Q: How is the backup primarily entering the building?  A: Floor Drain  Q: Would you like to request a specific 4-hour window for our response service?  A: NO  Q: Is this building protected by an MSD-owned pumping system?  A: No  Q: What type of building is this?  A: Single-Family Home  Q: How deep was the water/sewage at its deepest point?  A: Puddle around floor drain  Q: Is there insurance in place to cover this problem?  A: Unsure  Q: Please enter the Date this back up began.  A: 3/24/2023"</p>
Requested Date/Time	3/24/2023, 12:44 PM
Assigned To	HAYDEN MARSCHALL <a href="mailto:Hayden.Marschall@cincinnati-oh.gov">Hayden.Marschall@cincinnati-oh.gov</a>

**Crew Arrival**

Arrival Date/Time	3/24/2023, 2:08 PM
-------------------	--------------------

**SBU Form Pg 1 - Property Status**

Photo of House



Is the property backed up now? Yes

Photo of backup source





Was the property previously backed up?

Backup Location

Basement

Backup Depth

*Feet*

*Inches*

2

Backup Source

Floor Drain

### SBU Form Pg 2 - Photos and Plumber Information

Photos of house interior and exterior

(0 records)

Did the customer have a plumber?

No

### SBU Form Pg 3 - Upstream Manhole

Size of Mainline (in)

12

Upstream Manhole Number

23212002

USMH Photo

USMH Photo	Optional Comments - USMH

Upstream Manhole Condition

Open and Running

Does the USMH have a Float Level Indicator (FLI)?

No

Does the upstream manhole show signs of previous surcharge?

No

### SBU Form Pg 4 - Downstream Manhole

Downstream Manhole Number

23212003

DSMH Photo

DSMH Photo	Optional Comments - DSMH

Downstream Manhole Condition

Open and Running

Does the DSMH have a Float Level Indicator (FLI)?

No

### SBU Form Pg 5 - Cleanout Information

Is there an outside cleanout?

No

### SBU pg 6 - Final Comments

SBU Work Order Final Comments

Rear of building yard is underwater

Did you leave a SBU Field Form?



Field Form 8

Did you advise the customer to call a plumber? Yes

Do you have any additional photos to add? Yes

(2 records)

Additional Photos

Photo	Description
	Backyard
	No sign of surcharge

**Employees and Equipment**

(2 records)

Employee(s) on Job

*Name*

- HAYDEN MARSHALL
- White, Clarence

Vehicles/Equipment on Job

*Equipment on Job*

- 20890

(1 record)

**Complete Field Investigation**

Crew Leader Signature



Completion Date/Time

3/24/2023, 2:40 PM

**Work Order Cost**

Hours on Job	0.53344
Total Labor Cost	37.42
Total Equipment Cost	2.97
Total Work Order Cost	40.39